

**SECTION II**  
**NAVIGATION PUBLICATIONS**

**NM 48/99**

**USCG LIGHT LIST VOLUMES I - VII CORRECTIONS**

<b>VOLUME VII</b>	<b>Ed 1999</b>	<b>LAST NM 15/99</b>
Page xxiii; Delete Broadcast Site Whitefish Point:		
<b>WHITEFISH POINT</b>		Remove from list.
		*
(USCG)		48/99
Page xxiii; Delete Broadcast Site Neebish Island:		
<b>NEEBISH ISLAND</b>		Remove from list.
		*
(USCG)		48/99
Page xxiii; Add Broadcast Site Pickford:		
<b>PICKFORD</b>	<b>309 200</b>	<b>46 39 00 84 09 16 60 835</b>
(USCG)		48/99

**SAILING DIRECTIONS CORRECTIONS**

**PUB 191 8 Ed 1996 LAST NM 45/99**

Page 101—Line 31/R; insert after:

Areas to be avoided lie about 7 miles W of the S end and 6 miles NNW of the N end of Sandettie Bank. They have a radius of 500m and may best be seen on the chart.

(26(2346)99 Taunton) 48/99

**PUB 192 6 Ed 1994 LAST NM 39/99**

Page 60—Line 18/R; insert after:

Deep-draft vessels may be unable to navigate in the S approach.

During bad weather, pilots may only embark at the (Lowestoft North) boading position, in the vicinity of West Holm lighted buoy.

(BA NM 25/99) 48/99